

PCN – Product Change Notification

Topic:	Rollout of Firmware Release 4.00 in LEA-5H and LEA-5S		
	UBX-TN-08000		
Author:	TN		
Date:	18 Jan. 08		

We reserve all rights in this document and in the information contained therein. Reproduction, use or disclosure to third parties without express authority is strictly forbidden.

© 2008 u-blox ag.

1 Affected Products

Technology	Product Name	Order Number	Type No (Old)	Type No (New)	Remarks
u-blox 5	LEA-5H	LEA-5H-0	LEA-5H-0-003 LEA-5H-0-004	LEA-5H-0-005	
u-blox 5	LEA-5S	LEA-5S-0	LEA-5S-0-000 LEA-5S-0-001	LEA-5S-0-002	

2 Type of Change

[]	Hardware modification
[x	j	Firmware update
[]	Others,

3 Description of Change

u-blox has recently released the firmware version 4.00 for u-blox5 products. This firmware contains significant improvements in navigation performance, new features as well as bug fixes.

Details are summarized in the release notes [1].

4 Schedule

The rollout of LEA-5H and LEA-5S with the new firmware begins on January 18, 2008.

5 Customer Impact and Recommended Action

The u-blox 5 Firmware Version 4.00 is backward compatible to its predecessors 3.00. Customers in possession of older modules with one the data code listed in section 1 above may obtain the firmware image from u-blox and update them. Refer to http://www.u-blox.com/customersupport/ublox5 fw.html for the firmware images and http://www.u-blox.com/products/u_center.html for the firmware update utility.

Attention!

Do not attempt to download the new firmware in Engineering Samples with the data codes LEA-5H-0-000, LEA-5H-0-001 or LEA-5H-0-002.

6 Reference Documents

[1] u-blox 5 Firmware Version 4.00 Release Note, GPS.G5-SW-08002